# FP 115





#### nduct Representation - Actual Color May V

**METRIC** 

# TYPICAL APPLICATIONS

- For industrial splicing, start-up, tabbing, shingling and overlapping applications
- Effectively secures the paper to the core during roll start-up, holds the splice during processing and anchors the end of the roll securely
- Also ideal for tasks in which the tape must stick well to itself, including shingling and overlapping applications

# **PRODUCT FEATURES**

- Very high adhesion
- Quick bond and strong hold to smooth and porous papers, including 100 percent recycled paper
- Easy to start up and unwind
- Holds safely at ambient and elevated temperatures
- Resistant to moisture and humidity, which prevents the tape from lifting, puckering and curling
- · Hand-tearable

# CONSTRUCTION

Overall Grade/Function: High Performance

Backing: Flatback kraft paper Adhesive: Synthetic rubber-based

# STANDARD WIDTH(S)

48 mm 72 mm 96 mm

### STANDARD LENGTH(S)

55 m 60 vd

Contact your Shurtape sales representative for other available sizes

# **APPLICABLE STANDARDS**

ASTM D 6123/D 6123M-97 (2012), Type II

# COLOR(S)



PHYSICAL PROPERTIES

I III SIGAL I KOI EKIILS	SIANDAND	HEIMIO
Tensile Strength	40 lbs/in width	70.1 <b>N</b> /10 mm
Adhesion to Stainless Steel	70 oz/in width	7.66 N/10 mm
Thickness	6.5 mils	0.17 mm
Elongation	3%	3%
Maximum Service Temperature	120 F	49 C

STANDARD

Physical and performance characteristics shown above are obtained from tests recommended by PSTC, ASTM, government agencies or Shurtape Technologies, LLC, Quality Assurance and Technical Service departments and do not represent a guarantee of product performance. Individual rolls may vary slightly from these averages. The user should determine whether the product is fit for a particular purpose and is suitable for the user's method of application before use.

# STORAGE AND USAGE CONDITIONS

Tape should be stored in its original packaging in a cool, dry area away from direct sunlight and should be used within 12 months of date of shipment. Surfaces to which tape is applied should be clean, dry and free of grease, oil or other contaminants.

